# Maryland Historical Trust

Maryland Inventory of Historic Properties number:	55-23
Maryland Inventory of Historic Properties number: 76.6  Name: MD 320 (Pinytham)	JOVER DETHNEST BR
The bridge referenced herein was inventoried by the Maryland SH Historic Bridge Inventory, and SHA provided the Trust with eli The Trust accepted the Historic Bridge Inventory on April 3, 20 determination of eligibility.	gibility determinations in February 2001.
MARYLAND HISTORICA Eligibility Recommended	AL TRUST  Eligibility Not RecommendedX
	Eligibility Not RecommendedX
Eligibility Recommended	Eligibility Not RecommendedX
Eligibility Recommended  Criteria:ABCD Considerations:A	Eligibility Not RecommendedX
Eligibility Recommended  Criteria:ABCD Considerations:A	Eligibility Not RecommendedX

MHT No. <u>PG: 65-23</u>

# MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/ MARYLAND HISTORICAL TRUST

SHA Bridge No	<b>16065</b>	_Bridge name <u>MD</u>	320 (Piney Branch	Road) ove	r Northwes	t Branch
<u>LOCATION:</u> Street/Road na	me and nu	mber [facility carrie	ed] <u>MD 320 (Pine</u>	y Branch F	Road)	
City/town	Takoma Pa	rk		_Vicinity _	X	
County Pr	ince Georg	e's				
This bridge pro	ojects over:	Road Raily	way W	'ater <u>X</u>	L	and
Ownership: St	ate X	County	Municipa	ıl	Other _	
Nationa	cated with al Register-	n a designated histo listed district district	National Registe	r-determin	ed-eligible	district
Name of distri	ct					
BRIDGE TYPE Timber Bridge Beam B	:	Truss -Cover	ed Trestle	Timb	er-And-Coi	ncrete
Stone Arch Bri	dge					
Metal Truss B	ridge	<u></u>				
	e:   Lift		Single Leaf le		Iultiple Lea	
	Girder irder	Rolled G	irder Concrete Enc rder Concrete Enca			
Metal Suspens	ion					
Metal Arch						
Metal Cantilev	er					
Concrete	X: te ArchX	Concrete Slab	Concrete B	eam	Rigid Frai	ne
Other	Type Na	ame				<del></del>

<b>DESCRI</b>	<u>PTION:</u>			
Setting:	Urban	X	Small town	Rural

# **Describe Setting:**

Bridge 16065 carries MD 320 over Northwest Branch in Prince George's County. MD 320 runs east-west and Northwest Branch flows southeast. The bridge is located in the vicinity of Takoma Park in Northwest Branch Park, and is surrounded by a wooded area.

# **Describe Superstructure and Substructure:**

Bridge 16065 is a 1-span, 4-lane, concrete arch bridge. The bridge was originally built in 1910, and was widened with steel beams, a concrete deck, and a new railing in 1955. The structure is 18.3 meters (60 feet) long and has a clear roadway width of 17.7 meters (58 feet); there are 2 sidewalks each measuring 1.5 meters (5 feet) wide. The out-to-out width is 21.3 meters (70 feet). The superstructure consists of 1 arch which supports a cast-in-place concrete deck and concrete parapets with metal rails. The arch spans 17.1 meters (56 feet) and is a filled spandrel concrete arch. The concrete deck has a bituminous wearing surface. The structure has concrete parapets with metal railings and the roadway approaches have metal guardrails. The substructure consists of 2 concrete abutments. There are 4 flared concrete wingwalls. The bridge is not posted, and has a sufficiency rating of 93.6.

According to the 1996 inspection report, this structure was in satisfactory condition with patching and general light deterioration. The asphalt wearing surface is patched and spalling. The arch has areas with exposed reinforcement bars. The spandrel walls are spalling and have efflorescence. The metal beams are lightly rusting. The abutments and wingwalls have cracks and efflorescence. Also, the concrete parapet has collision damage, and part of the metal rail is bent and rusting.

### **Discuss Major Alterations:**

The bridge was widened in 1955 with a metal beam section. At the time of the widening, the parapets were replaced with a metal railing. The bridge has been patched numerous times, and most of the patches are failing.

# **HISTORY:**

WHEN was the bridge built:	<u>1910, 1955</u>		
This date is: Actual	X	Estimated	
Source of date: Plaque	Design plans _	County bridge	files/inspection form
Other (specify): State High	way Administration	Inspection Report/Brid	ige File

# WHY was the bridge built?

The bridge was constructed in response to the need for more efficient transportation network and increased load capacity.

## WHO was the designer?

Unknown

PG: 65-23

### WHO was the builder?

Unknown

# WHY was the bridge altered?

The bridge was widened to accommodate more traffic and to meet the roadway approaches of the widened road.

Was this bridge built as part of an organized bridge-building campaign?

Unknown

### **SURVEYOR/HISTORIAN ANALYSIS:**

This bridge may have Na	ational Register significanc	e for its asso	ociation with:
A - Events	B- Person		
C- Engineering/a	rchitectural character		

The bridge does not have National Register significance due to its widening with a metal beam section.

# Was the bridge constructed in response to significant events in Maryland or local history?

The advent of modern concrete technology fostered a renaissance of arch bridge construction in the United States. Reinforced concrete allowed the arch bridge to be constructed with much more ease than ever before and maintained the load-bearing capabilities of the form. As the structural advantages of reinforced concrete became apparent, the heavy, filled barrel of the arch was lightened into ribs. Spandrel walls were opened, to give a lighter appearance and to decrease dead load. This enabled the concrete arch to become flatter and multi-centered, with longer spans possible. Designers were no longer limited to the semicircular or segmental arch form of the stone arch bridge. The versatility of reinforced concrete permitted development of a variety of economical bridges for use on roads crossing small streams and rivers.

Maryland's roads and bridge improvement programs mirrored economic cycles. The first road improvement of the State Roads Commission was a 7 year program, starting with the Commission's establishment in 1908 and ending in 1915. Due to World War I, the period from 1916-1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920-1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund (with an equal sum from the counties) the building of lateral roads. The number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930.

By 1930, Maryland's primary system had been inadequate to the huge freight trucks and volume of passenger cars in use, with major improvements occurring in the late 1930's.

As the nation's automotive traffic increased in the early twentieth century, local road networks were consolidated, and state highway departments were formed to supervise the construction and improvement of state roads. With a diverse topographical domain encompassing numerous small and large crossings, Maryland engineers quickly recognized the need for expedient design and construction through the standardization of bridge designs.

The concept and practice of standardization was one of the most important developments in engineering of the twentieth century. In Maryland, as in the rest of the nation, the standardized concrete types became the predominant bridge types built. In the period 1911 to 1920 (the decade in which standardized plans were introduced), beams and slabs constituted 65 percent and arches 35 percent of the extant 29 bridges built in Maryland during this period. In the following decade, 1921-1930, the beam (now the T-beam) and slab increased to 73 percent and the arch had declined to 27 percent of the 129 extant bridges; in the next decade (1931-1940), the beam and slab achieved 82 percent and arches had further declined, constituting only 18 percent of the total of extant bridges built on state-owned roads between 1931 and 1946.

Although beam and slab bridges became the utilitarian choice, it appears that the arch was selected when aesthetic as well as other site conditions were considered. The architectural treatment of extant arch bridges supports this assessment. Many of these bridges were multiple span structures with open spandrels or masonry facing. Another decorative feature of the concrete arch bridge was an open, balustrade-style parapet. Despite the popularity of ornamental arches and the increase in use of beam and slab bridges, examples of simpler, single and multiple span closed concrete arch bridges with solid parapets continued to be constructed throughout the early twentieth century.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

Unknown

Is the bridge a significant example of its type?

A significant example of a concrete arch bridge should possess character-defining elements of its type, and be readily recognizable as an historic structure from the perspective of the traveler. The integrity of distinctive features visible from the roadway approach, including parapet walls or railings, is important in structures which are common examples of their type. In addition, the structure must be in excellent condition. This bridge, which was widened with a metal beam section, is an undistinguished example of a concrete arch bridge.

PG: 65-23

Does 1	the bridge	retain i	ntegrity of	important	elements	described	in	Context	Addendum	?
--------	------------	----------	-------------	-----------	----------	-----------	----	---------	----------	---

This bridge was widened in 1955, resulting the loss of such character-defining elements as the parapets and the arch section.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?

This bridge is not a significant example of the work of a manufacturer, designer, and/or engineer.

Should the bridge be given further study before an evaluation of its significance is made?


No further study of this bridge is required to evaluate its significance.


BIBLI(	OGRAPHY:		
_	v inspection/bridge files (list):	SHA inspection/bridge files	X
Johnso	on, Arthur Newhall		
1899	The Present Condition of Maryland Highway Maryland Geological Survey, The Johns Hopki		Maryland
	Spero & Company and Louis Berger & Associatistoric Highway Bridges in Maryland: 1631-19 Highway Administration, Maryland State D Maryland.	60: Historic Context Report. Mary	
Tyrrell	, H. Grattan		
	Concrete Bridges and Culverts for Both Railre Publishing Company, Chicago and New York.	oads and Highways. The Myron	C. Clark
<u>SURVI</u>	EYOR:		
Date b	ridge recorded December 1997		
Name	of surveyor Wallace, Montgomery & Associate	es / P.A.C. Spero & Company	

Organization/Address P.A.C. Spero & Co., 40 W. Chesapeake Avenue, Baltimore, MD 21204

**FAX number** (410) 296-1670

Phone number(410) 296-1635





1. PG:65-23 2. MD 320 over Northwest Branch

3. Prince George's Co., M.D. 4 Wallace, Montgomery & Assoc.

5. 12/97
6. MD SHPO
7. Elevation looking upstream

8. 1 of 4



- 1. PG:65-23
- 2. MD 320 over Northwest Branch
- 3. Prince George's Co., MD
- 4. Wallace, Montgomery & Assoc.
- 5. 12/97
- 6, MD SHPO
- 7. Elevation looking downstream
- 8. 2 of 4



- 1. PG:65-23
- 2. MD 320 over Northwest Branch
- 3. Prince George's Co., MD
- 4 Wallace, Montgomery & Assoc,
- 5. 12/97
- 6. MD SHPO
- 1. Looking East
- 8. 30 + 4



- 1. PG:65-23
  2. MD 320 over Northwest Branch
  3. Prince George's Co., MD
- 4. Wallace, Montgomery & Assoc, 5. 12/97
- 6. MD SHPO
- 7. Looking West
- 8, 4 of 4